

FIG. 1




FIG. 2

SURFACE RESISTIVITY	10^5	10^6	10^7	10^9	10^{10}	10^{11}	10^{13}
FINE NON-UNIFORM TONER (PULVERIZATION NOT ADJUSTED)	BAD	BAD	GOOD	EXCELLENT	GOOD	ORDINARY	BAD
FINE UNIFORM TONER (PULVERIZATION ADJUSTED)	ORDINARY	GOOD	GOOD	EXCELLENT	EXCELLENT	GOOD	BAD
COARSE TONE	GOOD	EXCELLENT	EXCELLENT	EXCELLENT	EXCELLENT	GOOD	BAD

(MEANING OF THE SIGNS (OFFSET-CONFIRMED STATUS))

EXCELLENT → OFFSET NOT NOTICED

GOOD → INSIGNIFICANT LEVEL OF OFFSET

ORDINARY → OFFSET NOTICED

BAD → HIGHLY SIGNIFICANT LEVEL OF OFFSET NOTICED

FIG. 3